

SSO Maintenance Report

Date of Occurance	Address	Blockage Reason 1	Blockage Reason 2	Volume/Gallons	Responsibility	Removal Method	Receiving Waters	Mitigation Used on Untreated Waters	Actions to mitigate future SSO
Date of Occurance	Address	Blockage Reason 1	Blockage Reason 2	Volume/Gallons	Responsibility	Removal Method	Receiving Waters	Mitigation Used on Untreated Waters	Actions to mitigate future SSO
01/13/14	2047 175th	Rain		25	Village	Sewer Jet			Line maintenance
01/13/14	18013 Gottschalk	Rain		25	Village	Sewer Jet			Line maintenance
02/25/14	17859 Golfview Ave	Rain		50	Homeowner	Sewer Jet			Line maintenance
03/14/14	18107 Dixie Hwy	Grease		50	Village	Sewer Jet			Line maintenance